





03056

Інструкція зі збирання


шир.:802мм-вис.: 531мм-гл.:400мм

28x ø 8x30 мм A1	10x ø 6,4x50 мм B1
1x R	10x B
2x 350mm M1	24x ø 3.5x16 мм E3
10x ø 5x30 мм C1	10x ø 16 мм D1
10x D2	1x G
4x K	60x Q
8x ø 4,5x25 мм E8	


№	a*b
1L+1R	510x382
2	768x80
3,3,3	768x62
4	802x400
5,5	796x230
6L,6L+6R,6R	360x130
7,7+7A,7A	711x130
8,8	740x358
9,9	796x194
10	L-793mm




1.



2.



3.



4.







Diagram 4 shows the front panel being attached to the side panel. The front panel is shown being moved into position, with dashed lines indicating the alignment of the screws. A circular callout with the number '4' is placed near the front panel.



4x 16 MM	 D1
4x	 D2



A square with two diagonals. The diagonal from the top-left corner to the bottom-right corner is labeled 'A'. The diagonal from the top-right corner to the bottom-left corner is labeled 'B'.

 $4x$


20x

K


Q

A1

Макс. 10мм



x2





8x

 $4x$  $4x$

B

$$A=B$$

20x



x2

1x

350mm

350mm

8x

Ø 3.5x16 MM



E3

1x



G

 $4x$


Ø 4,5x25 mm



E8



x2



3