





02063

Інструкція зі збирання


шир.:500мм-вис.:2113мм-гл.:400мм




36x ø 8x30 mm A1	34x ø 6,4x50 mm B1	42x ø 3.5x16 mm E3
1x R	34x B	4x K
3x 350mm M1	10x ø 16 mm D1	1x G
10x ø 5x30 mm C1	VAYS FURNITURE COMPANY	100x Q
10x D2	12x ø 4,5x25 mm E8	2x S

№	a*b
1L+1R	2092x382
2	468x80
3,3,3,3,3	468x62
4,4,4,4	468x382
5	502x400
6	496x398
7,7,7	496x322
8,8	496x338
9	L-468mm
10Lx3+10Rx3	360x130
11x3+11Ax3	409x130
12,12,12	358x438
13,13,13	496x194


1.




2.









3.



4.







5.









7.

A=B



02063




8.



9.



A=B









16x




x3

10.




x3

11.



12.

2x



6x



Ø 3,5x16 mm

E3

02063

