





05020








Інструкція зі складання

Габаритні розміри (Шир. / Вис. / Гл.):
1.40/0.42/0.40


26x ø 8x30 мм A1	2x ø 8x50 мм A2	1x G
1x R	2x 300mm M1	28x ø 3.5x16 мм E3
6x ø 6,3x34 мм C1	6x 15 мм D1	36x ø 3x20 мм E1
30x ø 6,4x50 мм B1	6x 18 мм D	8x ø 4x30 мм E8
30x 12 мм B	6x Y2	12x ø 3,5x20 мм E2
26x Q		8x U

№ - деталі, кількість	Розмір деталі
1L+1R	304x396
2	304x396
3,3	676x80
4	1400x396
5	1400x396
6	1396x332
7	1048x80
8,8	396x80
9L,9L+9R,9R	360x160
10,10+10A,10A	619x160
11,11	326x160
12,12	648x356
13,13	670x260








- 4x
 $\varnothing 6,4 \times 50$ mm B1
- 4x
 12 mm B




- 4x
 $\varnothing 6,4 \times 50$ mm B1
- 4x
 12 mm B




- 2x
 $\varnothing 8 \times 50$ mm A2





- 6x
 $\varnothing 6,4 \times 50$ mm B1
- 6x
 12 mm B




- 6x
 15 mm D1
- 6x
 18 mm D








- 26x  Q
- 6x  Y2
- 12x  E2
Ø 3.5x20 mm





A=B




- 10x  A1
Ø 8x30 mm
- 8x  B1
Ø 6,4x50 mm
- 8x  B
12 mm



A=B




A=B




05020

- 18x  E1
Ø 3x20 mm



x2





- 1x  M1
300mm

- 8x  E3
Ø 3.5x16 mm

- 4x  E8
Ø 4x30 mm

- 4x  U



x2

- 1x  G

